

Table of Contents

I. Introduction	p. 1-2
II. Map	p. 3
III. Major Buildings	
A- Building #607: <i>Infantry Barracks</i>	p. 1-13
i. Task One: Conditions Assessment:	p. 1
1. Site Context	
2. Exterior Assessment	
3. Interior Assessment	
ii. Task Two: Ultimate Treatment and Use	p. 8
1. Exterior	
2. Interior	
iii. Task Three: Requirement for Treatment	p. 11
1. Code Compliance	
2. Functional requirements	
iv. Task Four: Alternative Treatments:	p. 13
1. Viability of recommendations	
2. Advantages and Disadvantages of Alternative Treatment	
3. Specific recommendations	
4. Cost estimates	
B- Building #614: <i>Post Hospital</i>	p. 1-24
i. Task One: Conditions Assessment	p. 1
ii. Task Two: Ultimate Treatment and Use	p. 17
iii. Task Three: Requirement for Treatment	p. 22
iv. Task Four: Alternative Treatments	p. 24
C- Building #636: <i>Red Cross Convalescent House</i>	p. 1-18
i. Task One: Conditions Assessment	p. 1
ii. Task Two: Ultimate Treatment and Use	p. 12
iii. Task Three: Requirement for Treatment	p. 15
iv. Task Four: Alternative Treatments	p. 18
D- Building #638: <i>Double Artillery Barracks</i>	p. 1-17
i. Task One: Conditions Assessment	p. 1
ii. Task Two: Ultimate Treatment and Use	p. 10
iii. Task Three: Requirement for Treatment	p. 14
iv. Task Four: Alternative Treatments	p. 17
IV. Minor Buildings	
A- Building #621: <i>Hospital Sergeant's Quarters</i>	p. 1-9
i. Task One: Conditions Assessment	p. 1
ii. Task Two: Ultimate Treatment and Use	p. 5
iii. Task Three: Requirement for Treatment	p. 7

iv. Task Four: Alternative Treatments	p. 9
B- Building #626: <i>Dental Surgery</i>	p. 1-11
i. Task One: Conditions Assessment	p. 1
ii. Task Two: Ultimate Treatment and Use	p. 6
iii. Task Three: Requirement for Treatment	p. 9
iv. Task Four: Alternative Treatments	p. 10
C- Building #628: <i>Mess Hall and Kitchen</i>	p. 1-9
i. Task One: Conditions Assessment	p. 1
ii. Task Two: Ultimate Treatment and Use	p. 5
iii. Task Three: Requirement for Treatment	p. 7
iv. Task Four: Alternative Treatments	p. 9
D- Building #630: <i>Quartermaster's Storehouse</i>	p. 1-9
i. Task One: Conditions Assessment	p. 1
ii. Task Two: Ultimate Treatment and Use	p. 5
iii. Task Three: Requirement for Treatment	p. 7
iv. Task Four: Alternative Treatments	p. 9
E- Building #631: <i>Hospital Steward's Quarters</i>	p. 1-9
i. Task One: Conditions Assessment	p. 1
ii. Task Two: Ultimate Treatment and Use	p. 5
iii. Task Three: Requirement for Treatment	p. 7
iv. Task Four: Alternative Treatments	p. 9
F- Building #640 series, 602, 673, 676: <i>NCO Duplexes and garages</i>	p. 1-15
i. Task One: Conditions Assessment	p. 1
ii. Task Two: Ultimate Treatment and Use	p. 10
iii. Task Three: Requirement for Treatment	p. 13
iv. Task Four: Alternative Treatments	p. 15
v. Garages	p. 1 of 1
V. Bibliography/References	
VI. Volume II: Appendices	
A- Conditions Assessment Matrices per building	